

FACILITY COMPLIANCE AUDIT REPORT Division of Waste Management Solid Waste Section

UNIT	TYPE:	AND COLORS	7 4444	Marie Ediginariya		AM. Say	
Lined MSWLF	LCID	YW	Transfer	Compost		SLAS	COUNTY: Forsyth
Closed MSWLF	HHW	White goods	Incin	T&P	X	FIRM	PERMIT NO.: 34-22
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO		SDTF	FILE TYPE: COMPLIANCE

Date of Audit: August 7, 2009 Date of Last Audit: January 27, 2009

FACILITY NAME AND ADDRESS:

Slater Industries Treatment and Processing Facility 945 Valleystream Road Winston-Salem, NC 27104

GPS COORDINATES: N: 36.0817 E: -80.3678

FACILITY CONTACT NAME AND PHONE NUMBER:

Joe Slater, Owner and Operator c: 336-416-6097 f: 336-945-9727 jslater1@triad.rr.com

FACILITY CONTACT ADDRESS:

5334 Shallowford Road Lewisville, NC 27023

AUDIT PARTICIPANTS:

John Patrone, NCDENR – Solid Waste Section (SWS) Joe Slater, Owner and Operator

STATUS OF PERMIT:

Permit To Operate (PTO) issued July 26, 2005 PTO expires August 1, 2010

PURPOSE OF AUDIT:

Comprehensive Audit

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS:

None

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

AREAS OF CONCERN AND COMMENTS:

On August 7, 2009, John Patrone met with Joe Slater to conduct a comprehensive audit of the Slater Industries Treatment and Processing facility in Winston-Salem, Forsyth County.

- 1. The facility site plan and operations plan were reviewed.
- 2. The facility is a permitted Treatment and Processing (T&P) facility. It accepts Land Clearing and Inert debris (LCID) material. It produces mulch and boiler fuel and crushes concrete and asphalt. Brick and rock are stored for reuse and topsoil is screened-out and sold. Logs and large limbs suitable for milling are sawn and kiln-dried on-site.
- 3. Facility throughput of land clearing debris for July 2007 through June 2008 was 2,730 tons and for July 2008 through June 2009 was 1,600 tons.
- 4. The concrete block wall is routinely under construction. Forms are poured as concrete slurry or overrun is received.
- 5. The facility appeared to meet all required setbacks (50 ft buffers on the north and south sides and the existing buffer from Valleystream Road).
- 6. The facility maintains a portion of its lot on which operations are not conducted (flood prone area to the east).
- 7. During the inspection there were two piles of land clearing debris and four piles of mulch as well as piles of concrete, asphalt, and soil.
- 8. Mr. Slater estimates that the average single axel truck contains 6 to 10 yd³ of land clearing debris and that the average tandem axle truck contains 12 yd³.
- 9. Non-conforming waste is identified as it is off-loaded. Haulers are required to collect and haul-off their non-conforming waste.
- 10. There was no indication of soil erosion or runoff.
- 11. Proper signage was posted at the facility entrance.
- 12. The site is secured by a gate.
- 13. The facility's permit shall expire on August 1, 2010.

Please contact me if you have any questions or concerns regarding this audit report.

Mohn Patrone

Environmental Senior Specialist

Regional Representative

Phone: 336-771-5095 Fax: 336-771-4631

			r	 <u> </u>
Delivered on : August 11, 2009 by	Hand delivery	x	US Mail	Certified No. [_]

cc: Mark Poindexter, Field Operations Branch Supervisor
Jason Watkins, Central Regional Supervisor
Donald Herndon, Compliance Officer
Michael Scott, Composting & Land Applications Branch Head